SWISSALEBANON Rebuilding Beirut one house at a time

APARTMENT 2

Contact Information

Jihad Ghattas


Area: Beirut, Geitawi

Floor: First floor

Ownership: Privately owned

Furnished: Yes

Number of Residents: 4



Damage Assessment

Overall Damage

- Affected but habitable


1st Floor

Openings

- Broken windows and doors
- Damaged terrace area
- False ceiling destroyed

Structural Condition

- Safe




4.1000

Bill of Quantities for Renovation Works

Divison	Type Of Work	Zone	Specifications	Qty.	Total Price (USD)
1	Metal/Glass Works				
1.1	Aluminium window				
	W1	LIVINGROOM	130x 130 cm aluminum wall frame+sliding	1	690
	W2	LIVINGROOM	130 x 130 cm aluminum wall frame+sliding	1	500
	W3	BEDROOM 1	60 x 105 cm aluminum frame net needed	1	320
	W4	BEDROOM 1	132 x 120 cm aluminum wall frame+sliding	1	320
	W5	BEDROOM 2	135 x 120 cm aluminum wall frame+sliding	1	125
	W6	BEDROOM 2	135 x 120 cm aluminum wall frame+sliding	1	125
	W8	TERRACE	410 x 240 cm aluminum wall frame=sliding	1	1150
	W7	ENTRANCE	glass sheet 40 x 80 cm	1	80
	D1	LIVING ROOM	246 x 180 sliding aluminum wall frame sliding door	1	230
				Total	3540
2	Wood Works				
2.1	Doors				
	Repair Works	INTERIOR	Repair + Paint + Knobs		200
				Total	200
3	Civil Works				
	Maintenance/ Labor Work	BLDNG	Plaster + Demolition + Debris Removal	5	200
	Paint	INTERIOR	Interior Painting (Wall + Ceiling)	1	500
				Total	700
4	False Ceiling				
		KITCHEN	Repair works	1	75
		CORRIDOR	420 x 140 cm (60x60 gypsum boards)	1	250
				Total	325
	Sub-t		Sub-total	4765	
Miscellaneous				460	
Supervision Fees (15%)				714.75	
Grand Total				5939.75	





WORK PROCESS

