APARTMENT 6

SWISSALEBANON Rebuilding Beirut one house at a time

Contact Information

Boutros Assaf


Area: Mar mikhayel, facing Saliba market, next to La Tavolina restaurant

Floor: Ground floor, a small duplex

Ownership: Privately owned

Furnished: Damaged and poorly

Number of Residents: A family of four members with two toddlers



Damage Assessment:

Overall Damage


Affected but habitable

Openings

- $\checkmark~$ Broken glass with aluminum restoration
- \checkmark Broken doors inside the house
- ✓ Damaged kitchen cupboard area
- ✓ Back Door without glass
- \checkmark Water winch inside the house
- $\checkmark~$ Damaged paint

Structural Condition

Safe, requires maintenance to avoid leakage



Submission of Quotation for Renovations:

Apartment 6		Botrus Assaf		
Type Of Work	Zone	Specifications	Qty.	Total Price (USD)
Aluminium/Glass Works				
W1	LIVINGROOM	155 x 147 cm	1	330
W2	LIVINGROOM	155 x 120 cm	1	280
W3	BEDROOM	70 X 130 cm	1	170
W4	BEDROOM	116 x 62 cm	1	150
W5	BEDROOM	130 x 66 cm	1	170
W6	BEDROOM	120 x 50 cm	1	130
D1 /4	WC	82 x 200 cm	2	220
D2	LIVINGROOM	glass sheets(66*74/67*84/76*82/80*110cm)	4	220
D3	BEDROOM	88 x 220 cm	1	270
D5/6	BEDROOM	180 x 220 cm	2	450
			Total	2390
Civil Works				
Paint	APT	remove damaged wallpaper/ paint walls	1	1000
			Total	1000
			Supervision Fees	400
			Miscellaneous	500
			GrandTotal	4290

Damage Assessment / Before



Damage Assessment / Before



Work Progress:













